ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	**Street Name**	**Significant Landmark**
W0331, W0327, W0380, W0313, W0378	Lakshmi Sagar Lyt 6th Crs, Lakshmi Sagar Lyt North Side, 2nd Crs, 9th Crs Lakshmi Sagar Lyt, NA, 8	Gandhinagara opposite to MES School
Segment No.	**Total Length (m)**	
1/C-W0331/S032838	89.74	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	48.47	77.595209	13.099344	77.595628	13.099189	W0327	W0331
2	41.27	77.594601	13.100399	77.594560	13.100028	W0378	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Constructions of Drains Gandhinagara opposite to MES School in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	1000000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	DRAIN
Tender	**Work Details**	**Job No. / Work Code**
Tender	Constructions of Drains Gandhinagara opposite to MES School in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	001-17-000011
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK.D)E-PMT-08/WO/26/2017-18	02/05/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
04/06/2017	30/05/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K BASKAR		0.00
Phone No.	**E-Mail ID**	

9361

Field Inspection Details

Number of Trees	Any Other Information	Name
0		SACHIN
Date of Inspection	**Remarks**	
18/06/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0331, W0327, W0380, W0313,

in Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	18/06/2017	18/07/2017	COMPLETED
SE	VASU K M	18/06/2017	18/07/2017	COMPLETED
EE	VASU K M	18/06/2017	18/07/2017	COMPLETED
AEE	DEVARAJ	18/06/2017	18/07/2017	COMPLETED
AE	SACHIN	18/06/2017	18/07/2017	COMPLETED
AE	SACHIN	18/06/2017	18/07/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0331, W0327, W0380, W0313,